

8. Meter

Which directs measurements. The graduation above directs and the graduation impedance below directs SWR.

9. EXT. DC INPUT (upper surface)

The input terminal when an external power supply is used.

10. Store battery box (back) AA type dry battery.

